

A blacksmith is shown in profile, working at an anvil. Bright sparks are flying from the point of contact between the hammer and the anvil, creating a dramatic, high-contrast scene. The background is dark, making the glowing sparks and the blacksmith's form stand out.

THE SCIENCE OF BLACKSMITHING

Gaspar Lesznik

Artist - Blacksmith - Engineer

AU 2019

Disclaimer

- I don't shoe horses.
- Farriers shoe horses.
- All Farriers are Blacksmiths.
- Not all Blacksmiths are Farriers.

Topics

- Traditional Blacksmithing
- The Raw Material - Steel = Iron + Carbon
- Steel – the tough stuff
- Blacksmithing Equipment
- Forging
 - Temperatures and Physical State
 - Moving Metal - Physical and Mechanical
 - Heat Treatment
- Forge Welding

Traditional Blacksmithing

- A blacksmith makes tools and other objects out of metal by heating it and using force to bend, twist and otherwise shape the material.
- Before the Industrial Revolution (~1760 to 1840) the blacksmith was your local “factory” to make just about everything made of metal. Nails, chains, plows, pots, knives, chisels, hinges, latches, kitchen utensils, chains, etc.
- **Tools for all the Trades.**
- **Traditional** blacksmithing – how it has been done for thousands of years up until the industrial revolution (~1750 AD). (*my definition*)

The Raw Material: Steel = Iron + Carbon

- Iron (Fe) – *Latin: ferrum*
 - by mass is the most abundant element on earth, just ahead of oxygen, 32.1% and 30.1% respectively
 - Extracted from ores found on earth's crust and surface
 - Melts at ~2,750°F where it is separated from other minerals present
 - Relatively soft and malleable, dense
- Carbon (C) – *Latin: carbo (coal)*
 - Abundant in nature in many forms: coal, diamond, burnt toast.....
 - A building block of life. Without carbon life as we know it would not exist.

Steel - the tough stuff

- Steel is a **solid solution** of iron and carbon. The carbon is dissolved in the iron. Iron is the solvent and carbon is the solute.
- In 2020 the world produced 1,878 million tons of steel.
- Infinitely recyclable.
- There are over 3,500 grades of steel broken down into 4 categories
 - Carbon steel (90% of all steel produced).
 - Alloy steel
 - Tool steel
 - Stainless steel

Steel – the tough stuff

- Carbon Steel = Fe (~99%) + C (~<1%)
 - Mild (Low Carbon) Steel: C = < 0.25%
 - Inexpensive, the most abundant steel used globally (~90%). It is used in everything that does not require superior strength or durability.
 - Can not be hardened. Can not hold a sharp edge.
 - Piping, fencing, ornamental, wide range of structural applications (bridges)....
 - Medium Carbon Steel: C = 0.25 - 0.55%
 - Can be hardened.
 - Railroad tracks, machinery parts, pressure vessels, cranks.....
 - High Carbon Steel: C = 0.55 - 0.99%
 - Maximum strength and hardness, low ductility.
 - Knives, chisels, punches, spring steel, cutters,

Steel – the tough stuff

- Alloy Steels

- Contain one or more alloying elements (nickel, manganese, titanium, copper, silicon, chromium, molybdenum, cobalt, tungsten, vanadium, and aluminum) to obtain various steel properties for different applications.
- Hardenability, corrosion resistance, strength, formability, weldability, or ductility can be improved.
- More expensive than carbon steels. Widely available.
- Thousands of variations.

- Tool Steels

- A subset of alloy steels derived for material toughness, high hardness, abrasion resistance, heat resistance.
- Machine tools, hammers, molds, dies, cutters.....

- Stainless Steels

- Up to 20% chrome and 10% nickel. Corrosion resistant, sanitary, aesthetic.....

Steel – the tough stuff

- The carbon content determines the maximum *obtainable* hardness of the steel
- Heat treatment determines the *actual* hardness and flexibility
- How steel is heated and cooled will dictate whether the given steel will shatter, bend, or flex.
- Heat affects the growth and arrangement of the steel's crystalline structure
- *Wrought Iron*
 - *An iron alloy with <0.02% carbon and ~2% other impurities (slag)*
 - *Used throughout history but replaced by advanced steelmaking methods*
 - *No longer commercially available, last foundries shut down in the 1970's*

Four-digit AISI Alloy Numbering System

Note: Alloying elements are in weight percent, "xx" denotes carbon content.

10xx	Basic plain carbon steels	44xx	0.53 molybdenum
11xx	Plain carbon steel with high sulfur & low phosphorous (resulfurized)	46xx	0.85 or 1.83 nickel & 0.23 molybdenum
12xx	Plain carbon steel with high sulfur & high phosphorous	47xx	1.05 nickel, 0.45 chromium & 0.20 – 0.35 molybdenum
13xx	1.75 manganese	48xx	3.50 nickel, & 0.25 molybdenum
23xx	3.50 nickel (series deleted in 1959)	50xx	0.40 chromium
25xx	5.00 nickel (series deleted in 1959)	51xx	0.80 – 1.00 chromium
31xx	1.25 nickel & 0.60 chromium (series deleted in 1964)	5xxx	1.04 carbon & 1.03 or 1.45 chromium
33xx	3.50 nickel & 1.50 chromium (series deleted in 1964)	61xx	0.60 or 0.95 chromium & 0.13 – 0.15 vanadium
40xx	0.20 – 0.25 molybdenum	86xx	0.55 nickel, 0.50 chromium & 0.20 molybdenum
41xx	0.50 – 0.95 chromium & 0.12 – 0.30 molybdenum	87xx	0.55 nickel, 0.50 chromium & 0.25 molybdenum
43xx	1.83 nickel, 0.50 – 0.80 chromium & 0.25 molybdenum	88xx	0.55 nickel, 0.50 chromium & 0.35 molybdenum
		92xx	2.00 silicon

Steel – the tough stuff

- Junkyard Steels (my choice)
 - Used and abused and discarded steel of an unknown grade (and quality)
 - Widely available and cheap, often free
 - Infinite possibilities
 - Tool steel: Automobile springs (coil and leaf); axles, bed frames, saw blades, farm machinery, sucker rod, garage door springs.....
 - Carbon steel: Wrecking bars, fences, machinery parts and housings.....

Testing Junkyard Steel for Carbon

- Consider original use
- Spark test
 - Low or no carbon steels have dull sparks
 - Medium and high carbon steels are bright and explosive sparks



Blacksmith Equipment - the Forge

- Hearth or forge to heat metal.
 - Target high temperature from 1,700° to 2,300°F.
 - Usually constructed of cast iron, steel, brick and mortar
 - Must have forced air (oxygen). Blower, fan, bellows.....
- Fuel
 - Coal (clean bituminous is best). Widely available. Efficient and inexpensive.
 - Wood, charcoal can be used but very inefficient.
 - Propane
- Delivery of air (oxygen) is essential for a hot fire



Blacksmith Equipment – the Anvil

- Anvil (the soul of the smithy)
 - Acts as a mold, platform and third hand to shape the metal
 - Accepts various tooling for cutting, twisting, holding, etc.
 - Must have mass
 - Traditional anvils are expensive (~\$7 - \$9 per pound)
 - Any heavy metal block can work to degree
- Accessories
 - Vice, quench bucket(s), hammers, tongs, hand tools







Forging and Temperature

- Forging is the act of shaping metal with kinetic energy (tools and muscle)
- Heating steel to above its critical temperature ($\sim 1,350^{\circ}\text{F}$) changes the crystalline structure of steel making it malleable. A plastic state called austenite. Non-magnetic.
- Forging is typically done between $1,650^{\circ}\text{F}$ to $1,975^{\circ}\text{F}$
- As temperature drops the steel begins to harden and stresses develop. Forging at too low a temperature can crack or break the steel.
- Heating the steel above $2,000^{\circ}\text{F}$ can reduce the carbon content if held too long. Above $2,300^{\circ}\text{F}$ (dazzling white) the steel will begin to spark and burn.

Iron carbon phase diagram




Forging - Moving Metal

- Forging is fast.
 - Temperatures drop quickly. Be ready. Strike while the iron is hot.
 - The greater the mass the longer it stays hot.
 - But also radiates more heat making it more difficult to work
- Moving metal by forging is physical and mechanical
 - Hammers have different profiles to achieve different results
 - Possibilities are nearly endless

Forging - Color of Heat

- Blacksmith shops are dark for a reason
 - Peaceful
 - Adds to the mystery. Almost mystical.
- *Temperature is determined by color of the steel.*
 - Inexact but close enough
 - Everyone's eyes are different
 - Experience teaches



Fahrenheit	The Color of the Steel	
2000°	Bright Yellow	Forge Welding
1900°	Dark Yellow	
1800°	Orange Yellow	Forging
1700°	Orange	
1600°	Orange Red	
1500°	Bright Red	
1400°	Red	
1300°	Medium Red	
1200°	Dull Red	
1100°	Slight Red	
1000°	Very Slightly Red, Mostly Grey	

Heat Treatment

- Forging is violent
 - High temperatures
 - Hammering, twisting, bending....
 - The object being made takes on numerous stresses which must be relieved to avoid fracture.
 - At the same we want to create a hard, ductile tool that will withstand hard use. A chisel for example.
- The process to relieve the stresses and develop a finished tool is called Heat Treatment

Heat Treatment - Annealing

- To relieve all the stresses the object must be *annealed* or *normalized* to a relaxed molecular state.
- The tool is slowly heated to above the critical temperature (non-magnetic) then allowed to cool very slowly (in a dying fire, still air, insulated enclosure).
- This may be done 2 or 3 times to ensure the tool is fully annealed.
- A metal nirvana.
- Good time to do any necessary filing or grinding.

Heat Treatment - Hardening

- After annealing the tool is free of stresses but is too soft to do any work and must be hardened.
- Next step is to heat it up again above the critical temperature and the cool rapidly. Quenching.
- Different steels require different quench baths. Brine, water, oil, air. The rapid cooling is violent and must be done properly to avoid cracks and failure.
- Following quenching the tool is now 'glass hard'. A file will skim across it without scratching.
- Very hard and very brittle. If dropped it may shatter.
- The crystals created (martensite) from rapid cooling are unstable.

Heat Treating – Tempering

- Full hardening leaves the tool too brittle for use. It is hard but not tough. The hardness must be relieved in a controlled way.
- Tempering reduces hardness (stress) and increases ductility.
- The tool is slowly brought to a low heat which changes some of the hard crystals (martensite) to more ductile ferrite and cementite.
- Temperatures range from 400°F to 800°F
- It is a slow process and requires patience.

Tempering

- Steel is brought to a bright polish.
- Heat is slowly applied
- Color of the steel changes
- The darker the softer, more ductile
- By controlling heat distribution areas of hardness and ductility are also controlled.


Fahrenheit	The Color of the Steel	
2000°	Bright Yellow	Forge Welding
1900°	Dark Yellow	
1800°	Orange Yellow	Forging
1700°	Orange	
1600°	Orange Red	
1500°	Bright Red	
1400°	Red	
1300°	Medium Red	
1200°	Dull Red	Tempering
1100°	Slight Red	
1000°	Very Slightly Red, Mostly Grey	
800°	Dark Grey	
575°	Blue	
540°	Dark Purple	
520°	Purple	
500°	Brown/Purple	
480°	Brown	
465°	Dark Straw	
445°	Light Straw	
390°	Faint Straw	

Forge Welding

- By carefully controlling heat and eliminating contaminants, steel parts can be welded together to make one piece out of two or more.
- Different types of steel can be joined to utilize the properties of both. Combine strength and hardness with ductility. Reduce cost.
- Examples of forge welded common items are chain, axes and tomahawks, knives, Damascus steel, tongs, tools.....


Forge Welding

- Above $\sim 2,500^{\circ}\text{F}$ steel begins to melt.
- If 2 pieces of steel at that temperature touch each other they will stick together
- Speed and cleanliness are key. Any debris will weaken the weld.
- A flux (Borax) on the mating metals keeps them clean.



Forge Welding


- Layers of steel being welded into a larger billet
- ~2,000°F



Forge Welding - Damascus and Mokume Gane



Forge Welded Axe Head



- Tool steel blank
- Mild steel body



Questions?

THANK YOU!